Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/11011ME-0133
Work Order Type: Weatherization
Audit Name: 11011ME-0133

CLIENT INFORMATION

Client Name: NA Address:
Client ID: 11011ME-0133

Alt. Client ID: LOUDON

CLIENT CONTACT INFORMATION

NA Applicant/Person of Record

<u>AGENCY INFORMATION</u>

Agency: Mid-East Community Action Agency Agency Phone: (865) 248-8661

Address: P. O. Box 790

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Auditor - Kevin Human # 865-405-4386 Date - 3/22/10 Home Type - Site Built Primary Heat - Nat. Gas NO CERTIFIED FIRM/RENOVATOR REQUIRED

Measures Inspected Measure 1 Infiltration Redctn **Components Comment** WEATHERSTRIP D1 (GARAGE) ADJUST D2 & D3 TO CLOSE TIGHTER - (MOVE STRIKER PLATE IN WEATHERSTRIP IS IN GOOD CONDITION.) PANE REPLACEMENT WINDOW A6 APPROX. 34" X 30". Estimated Actual # Material / Labor **Description / Comment Units** Qty **Unit Cost** Total Qty **Unit Cost** Total 1 Miscellaneous Infiltration Reduction Each 1 Supplies Each 2 Labor Labor 1 Other Detail Sub Total: Measure Sub Total: Field Notes:

Measure 2 DWH Tank Insulation		Components				Inspected			
Comment			Fatimatad	•	Antivol				
			Estimated			Actual			
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
Hot Water Equipment	DHW Tank Insulation	Each	1						
2 Labor	Labor	Each	1						
Other Detail						7			
]	Sub Total:		
		Measure Sub Total:			Sub Total.				
Field Notes:									

Measure 3 DWH Pipe Insulation Comment		Components					Inspected	
			Estimated			Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
cost	cost for 10' of wrap							
2 Labor	Labor	Each	1					
Other Detail								
			Measur	e Sub Total:] ;	Sub Total:	
Comment REPLAC	all Bathroom Exhaust F CE BATH EXHAUST FAN RIC & SWITCH EXISTS. it to the Exterior		TER B					nspected
# ##= (= = = = / = = = = =	December 10 manager	11-11-	Estimated			Actual		
# Material / Labor	Description / Comment Bathroom exhaust fan	<i>Units</i> Each	Qty 1	Unit Cost	Total	Qty	Unit Cost	Total
 Health and Safety Items 	Datiliooni exhaust ian	Lacii	'					
2 Labor	Labor	Each	1					
Other Detail								
			Measur	e Sub Total:] ;	Sub Total:	
Field Notes:						1		
		Work O	rder Gra	and Total:		Gran	d Total:	

Report Run On: 5/25/2010